

Appendix 10 Photographs



PHOTOGRAPHIC LOG


Client Name: Safety-Kleen Corporation		Site Location: 300 Canal Street, Lawrence, Massachusetts	Project No. 30898-007
Photo No. 1	Date: 9/5/03		
Direction Photo Taken: Northwest			
Description: Recleaned Wall in Loading Dock Area			

Photo No. 2	Date: 9/5/03	
Direction Photo Taken: South		
Description: Consolidation and Compactor Room		



PHOTOGRAPHIC LOG

Client Name:

Safety-Kleen Corporation

Site Location:

300 Canal Street, Lawrence, Massachusetts

Project No.

30898-007

Photo No.

3

Date:

9/5/03

Direction Photo Taken:

South

Description:

General Waste Staging

**Photo No.**

4

Date:

9/5/03

Direction Photo Taken:

Southwest

Description:

Area Behind Compactor





PHOTOGRAPHIC LOG

Client Name:

Safety-Kleen Corporation

Site Location:

300 Canal Street, Lawrence, Massachusetts

Project No.

30898-007

Photo No.

5

Date:

9/5/03

Direction Photo Taken:

East

Description:

Alkaline Waste Storage -
Scarified Surface



Photo No.

6

Date:

9/5/03

Direction Photo Taken:

West

Description:

Flammable Waste
Storage Room -
Recleaned Wall





PHOTOGRAPHIC LOG

Client Name:

Safety-Kleen Corporation

Site Location:

300 Canal Street, Lawrence, Massachusetts

Project No.

30898-007

Photo No.

7

Date:

9/5/03

Direction Photo Taken:

West

Description:

Flammable Waste
Storage Room – Gray
Areas Are Hand Ground

**Photo No.**

8

Date:


9/5/03

Direction Photo Taken:

West

Description:

General Product Area
Waste Storage – Hand
Ground Areas in Gray





PHOTOGRAPHIC LOG

Client Name:

Safety-Kleen Corporation

Site Location:

300 Canal Street, Lawrence, Massachusetts

Project No.

30898-007

Photo No.

9

Date:

9/5/03

Direction Photo Taken:

North

Description:

Floor in Area C-20 With
Concrete Core Samples

**Photo No.**

10

Date:


9/5/03

Direction Photo Taken:

East

Description:

Alternate Acid Waste
Storage - Scarified
Surface





PHOTOGRAPHIC LOG

Client Name:

Safety-Kleen Corporation

Site Location:

300 Canal Street, Lawrence, Massachusetts

Project No.

30898-007

Photo No.

11

Date:


9/5/03

Direction Photo Taken:

East

Description:

Consolidation and Compactor Room – Area of Excavation and Core Sample Location

**Photo No.**

12

Date:

9/5/03

Direction Photo Taken:

East

Description:

Consolidation and Compactor Room – Area of Excavation and Core Sample Locations





PHOTOGRAPHIC LOG

Client Name:

Safety-Kleen Corporation

Site Location:

300 Canal Street, Lawrence, Massachusetts

Project No.

30898-007

Photo No.

13

Date:

9/5/03

**Direction Photo
Taken:**

North

Description:

Loading Dock Area of
Excavation - Sampling
Location and Sump

